

Microwave Fire Lessons Learned

Robert V Fox

December 2019



The INL is a U.S. Department of Energy National Laboratory
operated by Battelle Energy Alliance

Microwave Fire Lessons Learned

Robert V Fox

December 2019

**Idaho National Laboratory
Idaho Falls, Idaho 83415**

<http://www.inl.gov>

**Prepared for the
U.S. Department of Energy
Office of Nuclear Energy
Under DOE Idaho Operations Office
Contract DE-AC07-05ID14517**

CEM Mars 6 Incident

November 6, 2019
















FIBER OPTIC COMPONENT, HANDLE WITH CARE



Fiber Optic Temperature Sensor


Model: *Probe, RTP-300 Plus*

Part #: **314305**

Serial #: **TI4962D**

Gauge Factor: **4403506**

Range: **-40 TO 250°C**



FIBER OPTIC COMPONENT, HANDLE WITH CARE

Made in Canada

WARNING

USE RTP-300+ probe in a
on System. Improper
ol will result, and could
use a safety hazard.

Fiber Optic Probe Guide



MARS 5 & MARS 6™



MTS-300

P/N 314355

White probe with white end

Temperatures < 250 °C

MARS 6 only



MTS-300 High Temp

P/N 281461

White probe with black end

Temperatures > 250 °C

MARS 6 only




RTP-300+

P/N 314305

Blue probe with blue end

Temperatures < 250 °C

MARS 5 only



RTP-300+ High Temp

P/N 314306

Blue probe with black end

Temperatures > 250 °C

MARS 5 only


**RTP-300+ probes are not compatible with the MARS 6 unit as they are shorter than the MTS-300 probe and will not reach the bottom of the thermowell in the control vessel if used in the MARS 6.*

Run Time Report From microSD Card


- microSD card removed from the microwave and sent to CEM.
- Method running during the last run was “Mann Soil”. A 60-minute run.
 - Power = 1800 W
 - Ramp over 30 minutes to 170 °C.
 - Hold at 170 °C for 30 minutes.
- Software version 1.26. Latest MARS 6 software is version 1.51
- Thermocouple GF = 448-9482, Probe S/N TJ5009N, MTS-300 MARS 6 probe.
- Power/Temp./Time data from the final run was compared to previous Mann Soil runs that were successfully completed.
- Power/Temp. ramp consistently for ~22 minutes. At that 22 min. the temperature rise slows significantly and levels at ~141 °C. In response to the temperature lag the microwave went to full power 1800 W for ~14.5 minutes, but the temperature only went to ~149 °C. The run was aborted at 40.1 minutes by the ReactiGuard.
- CEM concludes that continued and prolonged application of 1800 W caused for over-heating and subsequent fire.

Runtime Data

Mann Soil_Previous Run vs Final Run



Mann Soil_Previous Run vs Final Run



Contributing Factors

- Blue Mars 5 thermocouple probe (16") used in a Mars 6 device. Incorrect S/N and GF.
- Unattended run. Acid fume sensor (optional, but not purchased) on exhaust line not used.

Additional Information: HPI

- Mars 5 thermocouple kept with Mars 6 spare probes and Mars 6 device.
- Mars 5 thermocouple fits into the Mars 6 connector and will not ERROR OUT.
- Thermocouple product boxes and labeling are similar. Probes not returned to their original boxes.
- At least 3 different colored warning labels containing 4 different warnings in probe boxes.
- A 100-page user manual that mentions nothing about Mars 5/Mars 6 part incompatibility.
- No known product recalls or other warnings for incompatible probes.

WARNING

NEVER use this BLUE RTP-300+ probe in a MARS 6 Digestion System. Improper temperature control will result, and could potentially cause a safety hazard.

P/N 602229

WARNING

This WHITE MTS-300 Probe is designed for the MARS 6 Digestion System, and SHOULD NOT be used in a MARS 5.

P/N 602230

Lessons.....Learned?

- CEM database showed the microwave was owned by a company located in North Carolina. INL Procurement using 3rd party vendors, who gets the updates?
- Cognizants listed in the CEM database for this instrument were INL staff present at the time of installation.
- User Manual revisions. Critical software revisions. Research staff not notified of updates.
- Storage of incompatible parts with compatible parts.
- Safety equipment listed as “optional” by the manufacturer. Equipment not purchased.
- New probe (safety-critical equipment) installed in a device w/o consulting manufacturer’s operating instructions or investigating specifics regarding the thermocouple.
- Incorrect serial# and Gauge Factor programmed into the instrument.
- No evidence of routine maintenance of the torque wrench.
- Over-reliance on equipment, the manufacturer, on past successful runs, and on personal knowledge/skills.
- Sign blindness. Bright orange WARNING label in the probe box.
- Conditioning/culture that enables us to ignore instructions and warning labels.