

F3502-0077-PL FMF Manifold Bypass, Vacuum System Assembly Parts List

April 1986

Doug Porter





DISCLAIMER

This information was prepared as an account of work sponsored by an agency of the U.S. Government. Neither the U.S. Government nor any agency thereof, nor any of their employees, makes any warranty, expressed or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness, of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. References herein to any specific commercial product, process, or service by trade name, trade mark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the U.S. Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the U.S. Government or any agency thereof.

F3502-0077-PL FMF Manifold Bypass, Vacuum System Assembly Parts List

Doug Porter

April 1986

Idaho National Laboratory Idaho Falls, Idaho 83415

http://www.inl.gov

Prepared for the U.S. Department of Energy Under DOE Idaho Operations Office Contract DE-AC07-05ID14517

REMARKS DRAWING NO. PART NAME OR DESCRIPTION MATERIAL Q MANIFOLD BYPASS F3502-0077-EC FLANGE, WELDING NECK, 2NPS ANSI 150# FLAT FACE WITH A FINISH OF 125 RMS OR BETTER, MATERIAL! NOTH A132 F304, PIPE, 2NPS SCHO 405(.154 WALL) MATL.: ASTM ABIZ TE304 ELBOURPIPE LR., WELDING FITTING, ZNPS SCHO 405, MATERIAL: METAN 19403 WP 304 TEE, PIPE, WELDING FITTING, 2 NPS SCHOGOS MAR L. & PETA A403 WASCH 557 THIS PARTS LIST IS
THE PR' RTY OF

ARBLINE

NATIONAL LABORATORY

ASSEMBLY

ASSEMBLY

ASSEMBLY

ASSEMBLY

ASSEMBLY

ASSEMBLY

OF

CHECKED

DRAWN

ASSEMBLY

ASSEMBLY

OF

CHECKED

DRAWN

ASSEMBLY

ASSEMBLY

OF

CHECKED

DRAWN

ASSEMBLY

OF

CHECKED

DRAWN

DRAWN

ASSEMBLY

OF

CHECKED

DRAWN

DRAW CHANGE ANLIAS (4-62) ENGINEERING PARTIFICROFILMED 7-2-86(0) **☆** GPO: 1984-755-130

The first of the f

