

435.36  
06/29/98  
Rev. 02

## NEW SITE IDENTIFICATION

### Part A – To Be Completed By Observer

1. Person Initiating Report: R. W. Jones	Phone: 526-4961
Contractor WAG Manager: Thomas M. Stoops	Phone: 526-4262
2. Site Title: STF-02 - STF Gun Range	
<p>3. Describe the conditions that indicate a possible inactive or unreported waste site. Include location and description of suspicious condition, amount or extent of condition and date observed. A location map and/or diagram identifying the site against controlled survey points or global positioning system descriptors shall be included to help with the site visit. Include any known common names or location descriptors for the waste site.</p> <p>Location: The STF Gun Range is located approximately 350' northeast of EOCR Bldg 601. Visual observation identified a high density of lead on the surface of the north berm. The walk-through was done on July 3, 1997, with the STF Range Master, Kevin Anderson. According to the Range Master several million rounds were expended into the berm.</p>	

### Part B – To Be Completed By Contractor WAG Manager

4.	<p>Recommendation:</p> <p><input checked="" type="checkbox"/> This site meets the requirements for an inactive waste site, requires investigation, and should be included in the INEEL FFA/CO Action Plan. Proposed Operable Unit assignment is recommended to be included in the FFA/CO. WAG: 10 Operable Unit: 10-04</p> <p><input type="checkbox"/> This site DOES NOT meet the requirements for an inactive waste site, DOES NOT require investigation and SHOULD NOT be included in the INEEL FFA/CO Action Plan.</p>
5.	<p>Basis for the recommendation:</p> <p>This site was previously not recommended for inclusion in the FFA/CO because it did not meet the requirements for an inactive waste site (KLF-204-97). Security has since clarified the inactive status of the Live Fire Range (HWS-03-98), stating that it has not been used since 1990. Based on this new information, the NSIF was revised to recommend the site for inclusion in the FFA/CO.</p> <p>The lead, copper and brass in the bullets and shells present a potential human health and ecological risk. The CERCLA site will be considered the berm soils (surface &amp; subsurface), the surface soils within 50 yards surrounding the berm, and the railroad ties in the front of the berm used for target practice.</p> <p>The CFA facility landlord will be responsible for removal of the firing house, the building north of the berm, and any stray gun range related material beyond the defined CERCLA site.</p> <p>Buildings will be re-evaluated prior to D&amp;D activities for potential threat of release.</p> <p>The basis for recommendation must include: (1) source description; (2) exposure pathways; (3) potential contaminants of concern; and (4) descriptions of interfaces with other programs, as applicable (e.g., D&amp;D, Facility Operations, etc.)</p>
6.	<p>Contractor WAG Manager Certification: I have examined the proposed site and the information submitted in this document and believe the information to be true, accurate, and complete. My recommendation is indicated in Section 4 above.</p> <p>Name: <u>Thomas M Stoops</u> Signature: <u>Thomas M Stoops</u> Date: <u>7.29.98</u></p>

### NEW SITE IDENTIFICATION

#### Part C – To Be Completed By DOE WAG Manager

7. DOE WAG Manager Concurrence:

WAG Operable Unit:

Concur with recommendation.

Do not concur with the recommendation. Explanation follows:

Name: \_\_\_\_\_ Signature: \_\_\_\_\_ Date: \_\_\_\_\_

#### Part D – To Be Completed By The INEEL FFA/CO Responsible Program Managers (RPM's)

8. FFA/CO RPM's Concurrence:

##### For DOE-ID

Name: Kathleen Hain Signature: *Kathleen Hain* Date: 7/29/98  Concur  
 Do not concur. Explanation follows:

##### For EPA Region X

Name: Wayne Pierre Signature: *Wayne Pierre* Date: 9/3/98  Concur  
 Do not concur. Explanation follows:

##### For State of Idaho

Name: Dean Nygard Signature: *Dean Nygard* Date: 10/19/98  Concur  
 Do not concur. Explanation follows: